## **Real Property Report**

Prepared By:	James Martin, N.L.S
Certified To:	LeGrow Brothers Property Equipment & Services Inc.
Address / Description:	Main Road, Pouch Cove, NL
Structures and Improvements:	A dwelling with a deck attached. All structures and improvements are contained wholly within the boundaries of the property surveyed unless mentioned below.
Apparent Encroachments and/or Comments:	The location of the boundaries are as per the found iron pin and also referencing the survey by James A. Martin, NLS. A service line extends in over the property to service the dwelling. The fences are constructed as shown on the attached plan. There is no visible evidence of any encroachments on subject property.
Reference Survey:	James A. Martin, NLS 06-13-2012 Job No. 073-2012
Surveyor's Certification:	This report and accompanying plan of James Martin, N.L.S. form an integral part of these returns and are not separable. This report has been prepared for the sole use and benefit of the parties named and is not valid unless it contains the original signature and stamp of the Newfoundland Land surveyor identified hereafter. I, James Martin, Newfoundland Land Surveyor, hereby certify that this Real Property Report was conducted under my supervision and is in accordance with the Newfoundland Land Surveyors Act RSN and the bylaws made thereafter.

Signed and Sealed at Flatrock, Newfoundland This 26<sup>th</sup> Day of April 2023

> James Martin, Newfoundland Land Surveyor, 2023 Unauthorized use, alteration or reproduction is prohibited by law as outlined in The Copyright Act.



